

**Service Information    No. 01/09****Date: 11.02.2009****Replacement of FCT Injection Pump Springs****M43**

This Service Information applies to all M43 engines equipped with injection pumps type G40011183. As a precautionary measure, we intend to replace the big spring of injection pumps type G40011183 and offer to carry out the exchange at no cost to the customer before commissioning of the engine.

Injection pumps type G40011183 contain the same type of big spring as injection pumps type G40011182. On some M43 engines equipped with injection pumps type G40011182 individual instances of breakage of the big spring have been reported. The probability of a breakage of the big spring in injection pumps type G40011183 is to be considered very low. However, in light of the aforesaid reports it cannot be completely excluded.

Investigations on the big springs contained in injection pumps type G40011182 pointed to variations in quality in the manufacturing process. In response to these findings the quality variations were eliminated immediately.

We sincerely regret the inconvenience caused to you by this necessary action. In order to allow the exchange of the big spring to be carried out in time before commissioning, your dealer will contact you to arrange all further details.